

50268

इंडियन ऑयल कॉर्पोरेशन लिमिटेड
Indian Oil Corporation Limited



Refinery & Marketing Division
Refinery: P.O. Hazira, Dist. Surat, Gujarat 393001, India
Marketing: P.O. Hazira, Dist. Surat, Gujarat 393001, India
Tel: 3774 5704, 3774 5741, 3774 5764

Am (11)

JUNE 27 1976

To:
Shri M. Khanna
Assistant General Manager
Estate Department
Reserve Bank of India
11, N.S. Road
Calcutta-70001

ED-94

Sub : Magnetic Water Conditioner

Upw. Div.

Please refer to your letter No. ED.9969/G.O. No. 0193-76 dated June 17, 1976 on the subject.

To minimize deposition of scale inside the tubes of coolers/condensers (heat exchanger) and prevent choking of gland cooling water lines of pumps 6 Nos of Magnetic Water Conditioner were installed in our refinery in January 76. Performance of these conditioners are satisfactory in dealing with scale deposition in water service as observed during recent inspection of above mentioned coolers/condensers as well as trouble free gland cooling water flow in the pumps under observation.

Hope the above meets your requirement.

Thanking you.

Yours faithfully

Chief Technical Services Manager

46

भारत सरकार, नई दिल्ली
श्री म. खन्ना, सहायक महाप्रबंधक, भू-संपत्ति विभाग, रिजर्व बैंक ऑफ इंडिया, 11, न.स. रोड, कलकत्ता-70001